

13 St Ann Street

Site Photo Report



Figure 1 View of property from Lower Church Street Car Park (North West)



Figure 2 View of property from St Ann Street (South View)



Figure 3 View in attic of property (Showing rafters and general condition)



Figure 4 View of stairway and hallway on ground floor (Front door is behind camera view)



Figure 5 View on entrance door and hallway on ground floor (Fuse box and notice board in view)



Figure 6 View of property from rear garden (North view)



Figure 7 View of entrance pathway to front door (Photo taken from entrance from St Ann Street road, at top of 4 steps)



Figure 9 View to indicate size of pane of glass (Tape measure for scale)



Figure 8 View of double window from inside of flat 1 on ground floor (North View)



Figure 10 View of current kitchen inside of flat 4 (South view)




Figure 11 View of top floor landing hallway (North View)



Figure 12 View of attic (Showing waste rainwater pipe)



Figure 14 View of window from outside of property (South view of flat 1 window from front pavement area)



Figure 13 View of outside window sill underneath flat 1 (South view from front pavement area)



Figure 15 View of living room in flat 6 showing single window frame and floorboard condition (North east view)