Railway Line Wood 2 County Wildlife Site.

EFD | E3.2
Rhododendron ponticum: Measures to treat, control and prevent its spread to be included in the CEMP.

EFF | E2.2, P3.1
Asset 17: Culverts north of Tan-yr-Allt cottages. Basic recording required.

EFF | P3.1
Asset 19: Revetment walls, North of Tai'r Meibion. Basic recording required.

EFD | E3.2
Temporary bat guidance fencing to be installed at locations of boundary removal where leading into underpasses and Railway Line Wood 2

EFD, EFH | E2.1
Stream 4 (underground): Method of construction working to avoid pollution or sedimentation of drains/watercourses. Statutory consent required for working in watercourse

EFD, EFH | E2.1
Stream 3: Method of construction working to avoid pollution or sedimentation of drains/watercourses. statutory consent required for working in watercourse

New farm access track

EFD | E3.2
Otter / badger proof fencing.

EFJ | P5.1
New stockproof fence along whole length of new field boundaries where affected.

EFA, EFB, EFD, EFJ | LE7.2
Translocated Hedgerow to reduce landscape impact and maintain habitat connectivity. Reptile watching brief required

VRF

Public Footpath No.43

Proposed woodland (LE2.1)

EFA, EFB, EFD, EFJ | LE7.2
Translocated Hedgerow to reduce landscape impact and maintain habitat connectivity. Reptile watching brief required

EFD | E3.2
Otter / badger proof fencing.

EFA, EFB, EFD, EFJ | LE 4.4
New hedgerow along northern side of County road to provide ecological, landscape and screening benefit

VR7 Tai'r Meibion

EFK | P4.4
Public footpath No.43 to be linked with County Road / NMU route to stop access to carriageway and increase safety and connectivity with the wider area

EFK | P4.4
Section of Public Footpath 43 to be closed for safety reasons.

EFF | P3.1
Assets 21-23: Tai'r Meibion farm: Grade II Listed Buildings and garden. Sympathetic landscaping on cutting and sympathetic reinstatement of any boundary walls affected

Tai'r Meibion cattle underpass

EFK | P4.4
Public footpath 42 to be diverted through the cattle underpass to create a safer means of crossing the carriageway and improve connectivity with the wider area

EFA,EFB,EFD,EFJ | LE4.4
New hedgerow to reduce landscape impact and increase habitat connectivity

EFF | P3.1
Asset 49: Road East of Tan-yr-Allt cottages to Crymlyn. Watching brief required

EFF | P3.1
Assets 13-16: Numbers 1-4 Tan yr Allt cottages: Grade II Listed Buildings
Sympathetic landscaping of new scheme cuttings

VR2 Tan-yr-Allt cottages

Public Footpath No.42

VRD

REFER TO FIGURE 7.7

REFER TO FIGURE 7.4



Seiliwyd ar fap yr Arolwg Ordnans gyda chaniatad Rheolwr Gwasg ei Mawrhydi.
Cedwir Hawlfraint y Goron.
Mae atgynhyrchu heb awdurdod yn torri hawlfraint y Goron a gall arwain at erlyniad neu achos sifil.

Based upon the Ordnance Survey mapping with the permission of the Controller of Her Majesty's Stationery Office.
Unauthorised reproduction infringes Crown copyright and may lead to prosecution or civil proceedings.
© Crown copyright
Welsh Assembly Government – 100017916 – 2016

CYNLLUN / SCHEME : A55 Abergwyngregyn to Tai'r Meibion Improvement

TEITL LLUNIAD / DRAWING TITLE : Environmental Masterplan 3 of 7

CLEIENT / CLIENT : Llywodraeth Cymru Welsh Government

DARLUNWYD GAN : DRAWN BY :	SW	DYDDIAD DARLUNWYD : DATE DRAWN :	26/05/2016
GWIRIWYD GAN : CHECKED BY :	CJ	DYDDIAD GWIRIWYD : DATE CHECKED :	26/05/2016
Taflen Sheet	3 of 7	GRADDFEYDD : SCALES :	1:2000@A3

Rhif Lluniad Drawing No. Figure 7.3

CYWI REV A

YGC