

Safety Patrol & Defect Log

| Date | Start time | End Time | Inspectors Name | Road Conditions | | | | Weather Conditions | | | | Route |
|------------|------------|----------|-----------------|-----------------|-----|------|-----|--------------------|------|------|-----|--|
| | | | | Dry | Wet | Snow | Ice | Fine | Rain | Snow | Fog | |
| 15-02-2020 | 09:30am | 15:00pm | [REDACTED] | | | | | | | | | <p>A470 C.B. Gwynedd/Mallwyd to Llanurig R/A – No Defect</p> <p>A44 – Llangurig R/A to C.B .Ceredigion (Eisteddfa Gerrig) – No Defect</p> <p>A489 – A470 Caersws junction to A483 Dolfor R/A/bypass. – No Defect</p> <p>A489 – Cemmaes Road R/A to A487 Machynlleth Clock – No Defect</p> <p>A487 – C.B.Ceredigion to C .B.Gwynedd (Dyfi Bridge) – No Defect</p> <p>Route driven in both directions.</p> |

Defect Details

