



IRIS CONTRACT HIGHWAY INSPECTIONS



INSPECTIONS BY ROUTE & DEFECTS LOGGED

**BATCH
NO** **INSPECTION DESCRIPTION**

78195 **SWTRA Safety Inspection (28 Day) of A40 East 28 Day on 05/01/2026**

Link/Section: - A40, 1004012005 - END 30 MPH - THE STEPS JN

WEATHER: Fine

SURFACE CONDITION: WET

INSPECTOR: [REDACTED]

Inspection Date: 05/01/2026 13:13:00

SURVEY METHOD: DRIVEN

NO DEFECTS FOUND DURING INSPECTION OF SECTION ON 05/01/2026

Link/Section: - A40, 1004012035 - THE STEPS JN - PYSGODLYN JN LHS

WEATHER: Fine

SURFACE CONDITION: WET

INSPECTOR: [REDACTED]

Inspection Date: 05/01/2026 13:16:00

SURVEY METHOD: DRIVEN

NO DEFECTS FOUND DURING INSPECTION OF SECTION ON 05/01/2026

Link/Section: - A40, 1004012046 - PYSCODLYN JN LHS - MARDY COTTAGE

WEATHER: Fine

SURFACE CONDITION: WET

INSPECTOR: [REDACTED]

Inspection Date: 05/01/2026 13:17:00

SURVEY METHOD: DRIVEN

NO DEFECTS FOUND DURING INSPECTION OF SECTION ON 05/01/2026

77720 **SWTRA Safety Inspection (28 Day) of A40 East 28 Day on 08/12/2025**

Link/Section: - A40, 1004012005 - END 30 MPH - THE STEPS JN

WEATHER: Raining

SURFACE CONDITION: WET

INSPECTOR: [REDACTED]

Inspection Date: 08/12/2025 10:55:00

SURVEY METHOD: DRIVEN

NO DEFECTS FOUND DURING INSPECTION OF SECTION ON 08/12/2025

Link/Section: - A40, 1004012035 - THE STEPS JN - PYSGODLYN JN LHS

WEATHER: Raining

SURFACE CONDITION: WET

INSPECTOR: [REDACTED]

Inspection Date: 08/12/2025 10:58:00

SURVEY METHOD: DRIVEN

NO DEFECTS FOUND DURING INSPECTION OF SECTION ON 08/12/2025

Link/Section: - A40, 1004012046 - PYSCODLYN JN LHS - MARDY COTTAGE

WEATHER: Raining

SURFACE CONDITION: WET

INSPECTOR: [REDACTED]

Inspection Date: 08/12/2025 10:59:00

SURVEY METHOD: DRIVEN

NO DEFECTS FOUND DURING INSPECTION OF SECTION ON 08/12/2025